



TECHNICAL BULLETIN

No: LTB00176
Issue: 1
Date: 05 MAR 2009

CIRCULATE TO:	Service Mgr	Warranty	Workshop	Body Shop	Parts
	X	X	X	X	X

SECTION: 501

Limited Seat Rock - Repair Procedure

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 8A474327 - 9A494400

Model Year: 2008 - 2009

Range Rover Sport (LS)

VIN: 8A163998 - 8A188559

Model Year: 2008

CONDITION SUMMARY:

Situation: When driving at low speed or accelerating in stop / start conditions, the driver and / or front passenger seat may exhibit a 'rocking' motion or a 'click' noise may be heard from the seat base. These may be caused by the seat track rubber bump stops compressing and not returning to their original shape.

Action: In the event of a customer concern of either of the above, refer to the Repair Procedure outlined below to replace the affected seat track(s).

PARTS:

LR012040Front seat track - non-memory Qty: 1

LR012041Front seat track - memory Qty: 1

TOOLS:

Refer to Workshop Manual (GTR) for any required special tools

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Time (hours)	Condition Code	Causal Part
Front seat track renew - LR3, Range Rover Sport	78.70.25	0.80	D4	HFP500200

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

REPLACE FRONT SEAT TRACK



NOTE: Global Technical Reference (GTR) lookup sequence is as follows:

GTR Home > NAS > Model > Service Information > Model Year > Workshop Manuals > 5: Body and Paint > 501: Body and Paint > 501-10: Seating

1. Refer to Workshop Manual (GTR) section 501-10: Seating (78.70.25) to replace the driver's or front passenger's seat track.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.
--