



TECHNICAL BULLETIN

No: LTB00118
Issue: 1
Date: 25 FEB 2008

CIRCULATE: TO

Service Mgr
X

Warranty
X

Workshop
X

Body Shop
X

Parts

SECTION: 204

Revised Workshop Procedure: Remove / Install Front Lower Suspension Arm

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 5A000360 - Onwards

Model Year: 2005 - Onwards

Range Rover Sport (LS)

VIN: 6A900302 - Onwards

Model Year: 2006 - Onwards

CONDITION SUMMARY:

Situation: A revised workshop procedure has been developed for the removal and installation of the front suspension lower arm. The previous procedure required the removal of the front hub/wheel assembly. The new procedure provides for the displacement of the driveshaft which will provide room for the arm to be removed.

Action: When removing / installing the front lower arm assembly, refer to the Repair Procedure outlined below.

PARTS:

No parts required.

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Old Time(Hours)	New Time (Hours)
Remove/install the suspension arm assembly/wishbone - Lower - LR3	60.35.02	1.10	1.0
Remove/install the suspension arm assembly/wishbone - Lower - Range Rover Sport	60.35.02	1.10	0.80

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

REMOVING / INSTALLING THE FRONT SUSPENSION LOWER ARM ASSEMBLY



NOTE: GLOBAL TECHNICAL REFERENCE (GTR) LOOKUP SEQUENCE IS AS FOLLOWS:
GTR HOME > NAS > MODEL > SERVICE INFORMATION > MODEL YEAR > WORKSHOP MANUALS > 2: CHASSIS > 204 SUSPENSION > 204-01: FRONT SUSPENSION - LOWER ARM (60.35.02).

1. Refer to Workshop Manual (GTR) Section 204-01: Front Suspension Lower Arm (60.35.02) for the revised removal / installation instruction.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.