



# TECHNICAL BULLETIN

No: LTB00121  
Issue: 1  
Date: 29 FEB 2008

CIRCULATE: TO

Service Mgr  
X

Warranty  
X

Workshop  
X

Body Shop

Parts

**SECTION: 307**

## Revised Workshop Procedure - Remove / Install Automatic Transmission Valve Body Assembly

### AFFECTED VEHICLE RANGE:

LR3 (LA) V8-only

VIN: 5A000360 - Onwards

Model Year: 2005 - Onwards

Range Rover Sport (LS)

VIN: 6A900129 - Onwards

Model Year: 2006 - Onwards

### CONDITION SUMMARY:

**Situation:** A revised workshop procedure has been developed for the removal and installation of the automatic transmission valve body assembly. The revised procedure removes the oil pan and valve body together, eliminating the removal of the engine mounts and engine lifting.

**Action:** When removing / installing the automatic transmission valve body, refer to the Repair Procedure outlined below.

### PARTS:

No parts required.

### WARRANTY:



**NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Old Time (Hours)	New Time(Hours)
Valve Body Assembly - Renew LR3	44.40.01	3.70	2.40
Valve Body Assembly - Renew Range Rover Sport	44.40.01	3.80	2.40

Normal warranty policy and procedures apply.

## REPAIR PROCEDURE

### REMOVING / INSTALLING THE AUTOMATIC TRANSMISSION VALVE BODY ASSEMBLY



**NOTE:** Global Technical Reference (GTR) lookup sequence is as follows:  
GTR Home > NAS > Model > Service Information > Model Year > Workshop Manuals > 3: Powertrain > 307: Automatic Transmission/Transaxle

1. Refer to Workshop Manual (GTR) Section 307-01A or 307-01B Automatic Transmission/Transaxle (44.40.01) for the revised removal / installation procedure.

**NOTE:** The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.