



# RECALL ACTION

Recall Action  
Number: P017

<b>Subject:</b>  <b>Brake Vacuum Assistance System</b>	Publication No.:	P017v6 Australia v4
	Model:	Discovery 3/LR3 2.7L TDV6
	Model Year:	2005-2009
	VIN Range:	LA000005 – LA513325
	Model:	Range Rover Sport 2.7L TDV6
	Model Year:	2005-2009
	VIN Range:	LS900002 – LS999999 LS100000 – LS215618
	Date of Issue:	19th July 2010

<b>To:</b>	<b>All National Sales Companies, Importers and Australian Dealers.</b>
<b>For the Attention of:</b>	<b>The Service Manager.</b>
<b>Copies To:</b>	<b>The Parts Manager, Service Reception, Workshop Supervisor, Workshop and Warranty Personnel.</b>

<b>Related Information:</b>	<b>This Recall Action is being reissued to notify dealers of the extension to the VIN ranges affecting additional EU3 vehicles.</b>  Specific vehicles in the VIN ranges LA412125 – LA487033, LS100008 – LS181999, LS980310 - LS999998 are eligible for Recall Action P008 which must be carried out at the same time as this Recall Action.
-----------------------------	--

## RE: Brake Vacuum Assistance System

**Urgent Note:** Where Discovery 3 and Range Rover Sport TDV6 **EU3** diesel vehicle has been repaired using **EU4 Brake Booster Vacuum Pipe part # LR018673**, these vehicles **MUST** be repaired again using the **EU3 Brake Booster Vacuum Pipe part # LR019703** (as the brake booster vacuum pipe is of a different design) and claimed via warranty as per the process included in this document.

Please check **DDW** to ensure the vehicle **EU specification** and if the Recall Action is outstanding prior to repair commencement.

Dear Colleagues

A concern has been identified on the above vehicles where oil is collecting in the brake booster causing a progressive loss of brake assistance, resulting in hard brake pedal and increased stopping distances for the same pedal effort. Engine oil in the brake master cylinder will lead to a loss of one or both of the foundation brake system hydraulic brake circuits and therefore increased brake pedal travel, increased stopping distances and, in the event of both primary and secondary brake master cylinder seal failure, a total loss of service brakes.

Temporary sticking of the non-return valve leads to a temporary loss of vacuum assistance on the braking system. The hydraulic braking system itself remains fully functional. Once the valve has unstuck the booster vacuum is immediately restored, full braking assistance is available, and the brakes perform normally for the remainder of that drive cycle.

### Action to be taken

Land Rover has taken the decision to recall affected vehicles and you will be required to replace the brake booster vacuum pipe, the vacuum pump non return valve and check for oil in the brake booster. Where oil is detected in the brake booster, the brake booster and if necessary master cylinder will be replaced. For the workshop procedure see Appendix 1.

Land Rover Australia will be writing to owners; requesting that the owner contact their nearest dealer, as soon as possible, to arrange for the vacuum pipe and valve to be replaced and/or associated components. Prior to recall letter mailing which will be dependant on material availability, Dealers are requested to contact owners of affected vehicles and repair.

**Dealers are reminded that they should not sell vehicles identified as affected by a safety recall until such time as the safety recall has been successfully completed on affected vehicles.**

**Please check DDW to ensure that the vehicle is affected by this Recall Action prior to undertaking any rework action. DDW will be updated to reflect only those vehicles affected. A listing of the 2005MY affected vehicles is attached to the bulletin as Appendix 3.**

**At the time of confirming a booking for vehicle repair, please ensure you check DDW and that all outstanding Field Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.**

For information purposes, a Technical Question and Answer document is attached as Appendix 2.

**Parts Information**

The parts from Table 1 should be ordered from Land Rover Parts in the normal manner.

**Table 1**

Part No.	Description	Drive	Model	Variant	Qty
LR014527	Master Cylinder Kit	RHD	Both	All	1
SJJ500090	Brake Booster Kit	Both	Discovery	All	1
SJJ500070	Brake Booster Kit	Both	RRS	Without Brembo Brakes	1
SJJ500080	Brake Booster Kit	Both	RRS	With Brembo Brakes	1
SIJ500040	Brake Fluid – 1Ltr	Both	Both	All	1
LR019703	Brake Booster Vacuum Pipe and Vacuum Pump Valve	RHD	Both	<b>EU3</b>	1
LR018673	Brake Booster Vacuum Pipe and Vacuum Pump Valve	RHD	Both	<b>EU4</b>	1

**Warranty Information**

**Table 2 – SROs**

Description	Trans.	SRO	Time
Check/replace vacuum pipe and Vacuum pump non return valve	Both	70.50.89.30	0.3
Check oil in brake booster and master cylinder	Both	70.50.89.31	0.1
Replace brake booster	Manual	70.50.01	1.1
Replace brake booster	Automatic	70.50.01	0.8
Replace master cylinder and brake booster	Manual	70.50.89.28	1.5
Replace master cylinder and brake booster	Automatic	70.50.89.28	1.3
Diagnose oil in brake booster - insufficient oil, re-fit original booster and master cylinder	Manual	70.50.89.32	0.6
Diagnose oil in brake booster - insufficient oil, re-fit original booster and master cylinder	Automatic	70.50.89.32	0.3
Drive in/drive out	Both	02.02.02	0.2







Warranty Claims should be submitted quoting program code **P017** together with option code X. In this instance it will also be necessary to quote the relevant SROs and parts from Tables 1 and 2.

**NOTE: The option that contains the drive in/drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.**

Warranty Claims should be submitted in accordance with the current Land Rover Warranty Policy and Procedures Manual and its amendments unless stated otherwise in this Recall Action.





**Attached**      **Appendix 1 – Workshop Procedure**  
                    **Appendix 2 – Technical Q & A**  
                    **Appendix 3 – Affected VIN Listing of 2005MY Outstanding EU3 vehicles.**



Appendix 1 – Workshop Procedure

Item	Description	
<b>Brake Booster Non-Return valve</b>		
1	<p><b>CAUTION:</b>  To avoid dirt or contamination entering the brake vacuum system ensure that prior to disconnection of the brake vacuum pipe and during the non return valve replacement the area around the brake vacuum pump is clean and clear of any debris.</p> <p>Pump the brake pedal until the brake vacuum assistance is exhausted.</p>	
2	<p>Remove the engine cover (see Fig. 1).</p> <ul style="list-style-type: none"> <li>• Remove the oil filler cap.</li> <li>• Release the 4 clips.</li> </ul>	 <p>E54295</p>
Fig. 1		
3	<p>Remove the fuel injector sound proofing (see Fig. 2).</p>	 <p>E114715</p>
Fig. 2		
4	<p><b>CAUTION:</b>  Always plug any open connections to prevent contamination.</p> <p>Disconnect the brake booster vacuum line from the brake vacuum pump (see Fig. 3).</p>	 <p>E55481</p>
Fig. 3		
5	<p><b>CAUTION:</b>  Failure to follow this instruction may cause damage to the vehicle.</p> <p>Remove and discard the brake vacuum pump upper inlet valve spigot (see Fig. 4).</p> <ul style="list-style-type: none"> <li>• Release the 2 clips.</li> </ul>	 <p>E118463</p>
Fig. 4		

<p>6</p>	<p>Remove and discard the brake vacuum pump inlet valve spring, ball and washer (see Fig. 5).</p>	<p>E118464</p>
<p>Fig. 5</p>		
<p>7</p>	<p>Remove the auxiliary battery cover.</p> <ul style="list-style-type: none"> <li>• Release the 2 clips (see Fig. 6).</li> </ul>	<p>E48702</p>
<p>Fig. 6</p>		
<p>8</p>	<p>Disconnect the brake booster vacuum hose from the brake booster (see Fig. 7).</p> <ul style="list-style-type: none"> <li>• Check for presence of oil in one way valve.</li> <li>• <b>If no oil presence in the one way valve, carry out steps 9 to 18 and release the vehicle.</b></li> <li>• <b>If oil is present in the one way valve, carry out steps 9 to 33.</b></li> </ul>	<p>E118473</p>
<p>Fig. 7</p>		
<p><b>Install</b></p>		
<p>9</p>	<p><b>CAUTION:</b>  Using a mirror ensure the correct orientation of the spring.</p> <p><b>CAUTION:</b>  Failure to follow this instruction may cause damage to the vehicle.</p> <p><b>CAUTION:</b>  If new components are damaged when installing a new valve kit must be used.</p> <p>Install the brake vacuum pump inlet valve spring (see Fig. 8).</p>	<p>E118465</p>
<p>Fig. 8</p>		

10	<p><b>CAUTION:</b>  Using a mirror ensure the correct orientation of the spring.</p> <p><b>CAUTION:</b>  Failure to follow this instruction may cause damage to the vehicle.</p> <p>Install the new brake vacuum pump inlet flat valve and washer (see Fig. 9).</p>	
11	<p><b>CAUTION:</b>  Make sure the O-ring is securely fitted to the spigot.</p> <p><b>CAUTION:</b>  Do not use excess force when fitting inlet valve spigot.</p> <p><b>CAUTION:</b>  Using a mirror make sure the spigot is securely fitted and undamaged.</p> <p><b>CAUTION:</b>  Failure to follow this instruction may cause damage to the vehicle.</p> <p><b>NOTE:</b> An audible click is heard when the clips are fully latched.</p> <p>Install the new brake vacuum pump inlet valve spigot (see Fig. 10).</p> <ul style="list-style-type: none"> <li>Secure with the clips.</li> </ul>	
12	<p><b>NOTE:</b> Connect the vacuum gauge to the valve and run the engine for 5 seconds. The gauge should maintain vacuum for at least 5 seconds with the engine not running. If the vacuum is not maintained the valve has been fitted incorrectly.</p> <p>Check the operation of the valve using a suitable vacuum gauge (see Fig. 11).</p> <ul style="list-style-type: none"> <li>Using a suitable cap blank off lower spigot.</li> </ul>	
13	<p><b>CAUTION:</b>  Always plug any open connections to prevent contamination.</p> <p><b>CAUTION:</b>  Make sure that a new component is installed.</p> <p>Connect the 2 new brake booster vacuum lines to the brake vacuum pump (see Fig. 12). <b>Note:</b> Ensure that correct EU3/EU4 Brake Booster Vacuum Pipe is fitted.</p>	

14	Install the injector sound proofing (see Fig. 13).	
		Fig. 13
15	Install the engine cover.	
16	Connect the brake booster vacuum hose.	
17	Install the cover( see Fig. 14).	
		Fig. 14
18	Start engine and check the brake booster operation.	
<b>Check for oil in the brake servo and master cylinder</b>		
<b>All vehicles</b>		
19	Pump the brake pedal until the brake vacuum assistance is exhausted.	
20	Remove the auxiliary battery cover (see Fig. 15). <ul style="list-style-type: none"> <li>• Release the two clips.</li> </ul>	
		Fig. 15
21	If installed, remove the auxiliary battery.	
22	Release the anti-lock brake system modulator (see Fig. 16). <ul style="list-style-type: none"> <li>• Remove the three nuts.</li> <li>• Release the brake tubes from the clip.</li> </ul>	
		Fig. 16
23	Disconnect the low brake fluid warning indicator switch electrical connector.	

	<p><b>CAUTION:</b>  Brake fluid will damage paint finished surfaces. If spilled, immediately remove the fluid and clean the area with water.</p> <p>Position an absorbent cloth to collect fluid spillage.</p>	
24	<p><b>Vehicles with manual transmission</b></p> <p>Disconnect the clutch master cylinder supply line (see Fig. 17).</p> <ul style="list-style-type: none"> <li>Using a suitable cap blank off the supply line.</li> </ul>	 <p>E52890</p>
		<p>Fig. 17</p>
25	<p><b>All vehicles</b></p> <p><b>CAUTION:</b>  Make sure the wings and trim panels are covered and protected, failure to follow this instruction may result in damage to the vehicle.</p> <p><b>CAUTION:</b>  Make sure that excessive force is not used when maneuvering Master Cylinder and ABS Modulator. Failure to follow this instruction may lead to movement of brake pipe joints, and air ingress into brake system and or fluid leaks.</p> <p><b>CAUTION:</b>  Move Master Cylinder, Brake Pipes and ABS Modulator assembly only a sufficient amount to gain access to master cylinder push rod. Taking care not to twist pipes in their unions (see Fig 18).</p> <p>Displace the master cylinder (see Fig. 18).</p> <ul style="list-style-type: none"> <li>Remove the two nuts.</li> <li>Check for oil deposit on master cylinder push rod.</li> </ul>	 <p>E118357</p>
		<p>Fig. 18</p>

26	<p>Check for oil ingress in brake booster (see Fig. 19).</p> <ul style="list-style-type: none"> <li>Using a suitable white cable tie check for oil ingress.</li> <li><b>If oil on the master cylinder push rod, install a new master cylinder (See (GTR), Workshop Procedure, section: 206-06).</b></li> <li><b>If oil is in the brake booster, install a new brake booster (See (GTR), Workshop Procedure, section: 206-07).</b></li> <li><b>If no oil in the brake booster and master cylinder, carry on from step 27.</b></li> </ul>	
		Fig. 19
<b>All vehicles</b>		
27	<p><b>CAUTION:</b> <b>Make sure the master cylinder is correctly aligned. Failure to ensure master cylinder is correctly aligned to the brake booster actuation rod may cause component damage or poor brake performance.</b></p> <p>Install the brake master cylinder.</p> <ul style="list-style-type: none"> <li>Tighten the nuts to 26 Nm (19 lb.ft).</li> </ul>	
28	<p>Secure the anti-lock brake system modulator.</p> <ul style="list-style-type: none"> <li>Install the three nuts.</li> <li>Secure the brake tubes to the clip.</li> </ul>	
29	<p>Check the security of the brake pipe to brake master cylinder and brake pipe to anti-lock brake system modulator unions and tighten to 15 Nm if required.</p>	
<b>Vehicles with manual transmission</b>		
30	<p>Connect the clutch master cylinder supply line.</p> <ul style="list-style-type: none"> <li>Remove cap.</li> </ul>	
<b>All vehicles</b>		
31	<p>Connect the low brake fluid warning indicator switch electrical connector.</p>	
32	<p>If installed, install the auxiliary battery.</p>	
<b>Vehicles with manual transmission</b>		
33	<p>Bleed the clutch system (see Global Technical Reference (GTR), Workshop Procedure, section: 308-00).</p>	
<b>All vehicles</b>		
34	<p>Start engine and check the brake booster operation.</p>	
35	<p><b>Endorse the Service Portfolio book with the Recall Action number and complete and attach the Recall Label (LSTPR1516, Sample Below) to the 'A' pillar R/H/S. Labels can be obtained via Haynes Bookworks – phone # 02 8713 1400. email <a href="mailto:sales@bookworks.com.au">sales@bookworks.com.au</a></b></p>	

**"VEHICLE SAFETY  
RECALL"**

**RECTIFICATION DETAILS**

RECALL No.: P017  
DATE: 6/8/09  
DLR CODE: xxxxx

RECALL No.:  
DATE:  
DLR CODE:  
RECALL No.:  
DATE:  
DLR CODE:

## Appendix 2 – Technical Q &amp; A.

<h1>Technical Q&amp;A</h1>	
<b>FOR USE ON INQUIRY</b>	
<b>Recall Extension Land Rover P017</b>	
<b><i>Discovery 3 and Range Rover Sport TdV6 Only</i></b>	

**Main Message:**

Land Rover have determined that oil migration condition described below may also now affect vehicles manufactured from May 2004 rather than the originally identified start point of November 2005. As a result, safety recall P017 has been extended to encompass this increased number of vehicles.

Land Rover has identified two concerns that affect the braking performance on its range Rover Sport and Discovery 3 TDV6 vehicles. Investigations have identified that the brake vacuum servo can become contaminated with engine oil migrating in to the brake booster or exhibit a sticking non return valve within the engine driven brake vacuum pump depending upon when the vehicle was built.

**Oil Migration Condition**

Customers have reported a reduction in braking assistance performance, and upon investigation dealer technicians report finding oil in the brake booster. When the engine is turned off the non-return valve in the vacuum pump does not in all cases seal. This allows engine oil to be sucked into the vacuum hose that feeds the brake booster (due to by-design residual depression in the brake booster feed hose). Oil may then migrate from the hose into the brake booster, which can lead to a reduction in brake assistance. Eventually the oil may migrate through the brake booster into the brake master cylinder where the main and primary & secondary pumping chamber seals may swell and could fail to seal.

Vehicles manufactured between May 2004 and April 2007 are at most risk of experiencing this condition. A modified vacuum pump was introduced in April 2007 to mitigate against this oil migration.

**Valve Sticking Condition**

The symptom has been identified as the brake vacuum pump not replenishing the vacuum in the brake booster for up to 60 seconds from engine-on, due to the pump non return valve "sticking" in the closed position. If the brake pedal is depressed typically 3-5 times within this time the brake booster vacuum becomes depleted and braking assistance is lost. Typically, within 60 seconds from engine-on the valve unsticks, the brake booster vacuum is restored and full braking assistance is available. Based on field reports, no further brake assistance symptoms are then experienced during that drive cycle.

**Q1 Why is Land Rover recalling certain models?**

A Oil collecting in the brake booster causes a progressive loss of brake assistance, resulting in hard brake pedal and increased stopping distances for the same pedal effort. Over time engine oil may migrate from the vacuum booster into the brake master cylinder which can lead to a loss of one or both of the foundation brake system hydraulic brake circuits and therefore increased brake pedal travel, increased stopping distances and, in the event of both primary and secondary brake master cylinder seal failure, a total loss of service brakes.

Temporary sticking of the non-return valve (NRV) leads to a temporary loss of vacuum assistance on the braking system, typically 60 seconds, on initial engine start up, the problem is most prevalent when vehicles have been left parked overnight in near-freezing weather (-5 to +5 degrees centigrade).. The hydraulic braking system itself remains fully functional. Once the valve has unstuck the booster vacuum is immediately restored, full braking assistance is available, and the brakes perform normally for the remainder of that drive cycle.

**Q2 Can you tell me more about what is wrong with the vehicles?**

A The brake vacuum system becomes contaminated with engine oil leading to reduced performance, and in severe cases further migration of the oil into the master cylinder can lead to seal damage which in the event of both primary and secondary brake master cylinder seal failure, leads to a total loss of service brakes.

For the sticking NRV condition the valve within the vacuum pump sticks to its seat preventing a supply of vacuum to the booster for a period of up to 60 seconds. This lack of vacuum for a very short time can lead to a hard brake pedal and increased pedal effort to stop the vehicle in the same distance as normal.

**Q3 Does this recall affect vehicle safety?**

A In the event that the brake booster becomes contaminated with engine oil the customer will notice a harder brake pedal and increased stopping distance for the same pedal effect, the customer will notice the need for greater pedal effort in order to stop in the required distance. If the oil has damaged the brake master cylinder seals, the customer may experience loss of one or both braking circuits. With the sticking NRV foundation (hydraulic) brakes remain fully functional, however, the customer may perceive that the brake performance is significantly reduced due to the increased pedal efforts required to slow the vehicle down.

**Q4 Has Land Rover received many complaints?**

A To date there have been a significant number of field reports and customer complaints relating to these two conditions.

**Q5 Have there been any accidents or injuries?**

A There have been 9 minor accidents reported to Land Rover where one of these conditions allegedly led to the accident. Land Rover is unaware of any allegations of injury in relation to these concerns.

**Q6 How was the condition discovered?**

A These conditions were both reported to Land Rover by dealers from around the world.

Customers have reported a reduction in braking assistance performance, and upon investigation dealer technician's report finding oil in the brake booster or temporary sticking NRV's.

- Q7 What has Land Rover done in production?**  
A A revised vacuum pump was introduced into production with an internal vent to minimize the brake booster oil ingress to an acceptable level in April 2007. The specification of engine that utilized this later specification vacuum pump that exhibited a sticking NRV is no longer in production.
- Q8 What will authorized repairers do to the vehicles?**  
A Authorized repairers will fit a modified vacuum pipe with an additional connection to the vacuum pump secondary outlet port, a revised NRV within the vacuum pump and an additional vacuum NRV at the highest point in the vacuum pipe. For vehicles which are at risk from the oil migration concern, authorized repairers will also inspect the brake booster and master cylinder for signs of oil contamination and replace affected components as necessary.
- Q9 Which vehicles are affected by this recall?**  
A Discovery 3 and Range Rover Sport 2006 – 2009 MY with 2.7 TdV6 engines.
- Q10 Are parts available to rework vehicles?**  
A Parts will be available by the time of customer receive their letters.
- Q11 How much will the recall cost Land Rover?**  
A Cost is never a factor in Land Rover's decisions to recall vehicles.
- Q12 How do I know if my Discovery/Range Rover Sport is affected?**  
A All owners of potentially affected vehicles will receive a letter shortly inviting them to contact a Land Rover authorized repairer for the work to be carried out.
- Q13 Can customers check their own vehicles?**  
A There are some indications in relation to oil migration of the concern being present. These include increased brake pedal effort to get the same degree of deceleration and harder than normal brake pedal feel. Some customers have also reported hearing a 'bubbling' or 'boiling' type noise when braking, caused by oil in the brake booster. Land Rover recommends that if any customer has a concern with the brake performance of their vehicle that they contact their authorised repairer immediately to seek further guidance.
- Q14 How long does it take for the car to be inspected and repaired?**  
A The work to be carried out is expected to be completed in approximately 2 hours. Due to dealer schedules, vehicles may be required for longer.
- Q15 Can I continue to drive my vehicle safely until it has been recalled?**  
A Customers can continue to drive their vehicles providing that there is no detectable reduction in braking performance. Should the customer have any concern that the braking system performance is reduced they should contact there authorized repairer immediately for further guidance.
- Q16 Why is Land Rover extending the range of vehicles being recalled?**  
A Land Rover's investigation that led to the launch of the P017 recall identified a start point of vehicle identification numbers LA 367110 for Discovery 3 and LS 929086 for Range Rover Sport. Land Rover continued to monitor field reports and warranty claims following the launch of the P017 recall. Reports of a similar condition to that covered in recall P017 were being progressively received for vehicles prior to the start point of the originally recalled vehicle population. Further engineering investigations concluded that the same symptoms and effect on vehicle operation were being experienced on vehicles prior to the start point of the original P017 recall. Land Rover has extended the P017 recall to cover those vehicles built prior to the original recall start point

**Note:** Please ensure that any Press enquiries are referred to the Land Rover Public Affairs office

**Appendix 3 – Affected VIN Listing of 2005MY EU3 Vehicles.**

VIN - EU3	Vin - EU3	VIN - EU3	VIN - EU3
SALLAAA175A000367	SALLAAA135A322987	SALLAAA135A324354	SALLAAA135A325757
SALLAAA135A000445	SALLAAA175A323017	SALLAAA135A324356	SALLAAA135A325761
SALLAAA135A000453	SALLAAA135A323025	SALLAAA135A324360	SALLAAA135A325762
SALLAAA135A000466	SALLAAA135A323034	SALLAAA135A324361	SALLAAA175A325779
SALLAAA135A000467	SALLAAA135A323041	SALLAAA135A324369	SALLAAA135A325843
SALLAAA135A000468	SALLAAA135A323143	SALLAAA135A324379	SALLAAA175A325873
SALLAAA135A000469	SALLAAA135A323514	SALLAAA135A324387	SALLAAA135A325878
SALLAAA175A000470	SALLAAA135A324006	SALLAAA135A324429	SALLAAA135A325901
SALLAAA135A000471	SALLAAA135A324021	SALLAAA135A324437	SALLAAA135A325936
SALLAAA175A000472	SALLAAA135A324091	SALLAAA135A324494	SALLAAA135A325947
SALLAAA135A000473	SALLAAA135A324093	SALLAAA135A324608	SALLAAA135A326021
SALLAAA175A000532	SALLAAA135A324099	SALLAAA135A324615	SALLAAA135A326159
SALLAAA135A000620	SALLAAA135A324101	SALLAAA175A324619	SALLAAA135A326292
SALLAAA135A000649	SALLAAA135A324112	SALLAAA135A324657	SALLAAA135A326332
SALLAAA135A000665	SALLAAA135A324127	SALLAAA135A324676	SALLAAA135A326343
SALLAAA135A000676	SALLAAA135A324136	SALLAAA135A324757	SALLAAA135A326386
SALLAAA135A000782	SALLAAA135A324149	SALLAAA135A324761	SALLAAA135A326410
SALLAAA135A000870	SALLAAA135A324168	SALLAAA135A324810	SALLAAA135A326414
SALLAAA135A000890	SALLAAA135A324173	SALLAAA135A324843	SALLAAA135A326438
SALLAAA135A000891	SALLAAA135A324174	SALLAAA135A324862	SALLAAA135A326543
SALLAAA135A000896	SALLAAA135A324183	SALLAAA135A324886	SALLAAA135A326559
SALLAAA135A000993	SALLAAA135A324192	SALLAAA135A324926	SALLAAA135A326644
SALLAAA175A300001	SALLAAA135A324203	SALLAAA135A325008	SALLAAA175A326668
SALLAAA135A300002	SALLAAA135A324204	SALLAAA135A325013	SALLAAA135A326696
SALLAAA135A300020	SALLAAA135A324212	SALLAAA135A325022	SALLAAA135A326748
SALLAAA135A300102	SALLAAA135A324228	SALLAAA135A325056	SALLAAA135A327077
SALLAAA175A300121	SALLAAA135A324232	SALLAAA135A325121	SALLAAA135A327081
SALLAAA175A300141	SALLAAA135A324233	SALLAAA135A325123	SALLAAA135A327082
SALLAAA135A300202	SALLAAA135A324240	SALLAAA135A325135	SALLAAA135A327083
SALLAAA135A300322	SALLAAA135A324244	SALLAAA135A325158	SALLAAA135A327089
SALLAAA135A317865	SALLAAA135A324249	SALLAAA135A325198	SALLAAA135A327090
SALLAAA135A317867	SALLAAA135A324252	SALLAAA135A325250	SALLAAA135A327093
SALLAAA135A318306	SALLAAA135A324267	SALLAAA135A325279	SALLAAA135A327097
SALLAAA135A318313	SALLAAA135A324273	SALLAAA135A325326	SALLAAA135A327150
SALLAAA135A318315	SALLAAA135A324277	SALLAAA135A325401	SALLAAA135A327211
SALLAAA135A318319	SALLAAA135A324280	SALLAAA135A325457	SALLAAA135A327217
SALLAAA135A319107	SALLAAA135A324281	SALLAAA135A325461	SALLAAA135A327225
SALLAAA135A319108	SALLAAA135A324296	SALLAAA135A325512	SALLAAA135A327266
SALLAAA135A319109	SALLAAA135A324297	SALLAAA135A325540	SALLAAA135A327298
SALLAAA135A319110	SALLAAA135A324300	SALLAAA135A325554	SALLAAA135A327299
SALLAAA135A322548	SALLAAA135A324306	SALLAAA135A325580	SALLAAA135A327304
SALLAAA135A322594	SALLAAA135A324307	SALLAAA175A325623	SALLAAA135A327305
SALLAAA135A322661	SALLAAA135A324312	SALLAAA135A325635	SALLAAA135A327321
SALLAAA135A322678	SALLAAA135A324313	SALLAAA135A325689	SALLAAA135A327338
SALLAAA135A322709	SALLAAA135A324317	SALLAAA135A325706	SALLAAA135A327376
SALLAAA135A322712	SALLAAA135A324321	SALLAAA135A325707	SALLAAA135A327379
SALLAAA175A322727	SALLAAA135A324324	SALLAAA135A325712	SALLAAA135A327408
SALLAAA135A322732	SALLAAA135A324338	SALLAAA135A325715	SALLAAA135A327455
SALLAAA135A322972	SALLAAA135A324348	SALLAAA135A325748	SALLAAA135A327463
SALLAAA135A322979	SALLAAA135A324352	SALLAAA135A325750	SALLAAA135A327475

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA135A327480	SALLAAA175A330124	SALLAAA135A331953	SALLAAA135A333467
SALLAAA135A327486	SALLAAA135A330697	SALLAAA135A331959	SALLAAA135A333493
SALLAAA135A327498	SALLAAA135A331171	SALLAAA135A331980	SALLAAA135A333507
SALLAAA135A327508	SALLAAA135A331226	SALLAAA135A332141	SALLAAA135A333513
SALLAAA135A327522	SALLAAA135A331275	SALLAAA135A332229	SALLAAA135A333576
SALLAAA135A327585	SALLAAA135A331285	SALLAAA135A332239	SALLAAA175A333587
SALLAAA135A327634	SALLAAA135A331350	SALLAAA135A332256	SALLAAA135A333592
SALLAAA135A327650	SALLAAA135A331357	SALLAAA175A332265	SALLAAA135A333598
SALLAAA135A327753	SALLAAA175A331382	SALLAAA135A332304	SALLAAA135A333613
SALLAAA135A327801	SALLAAA135A331394	SALLAAA135A332333	SALLAAA175A333618
SALLAAA135A327804	SALLAAA135A331402	SALLAAA135A332343	SALLAAA135A333636
SALLAAA135A327805	SALLAAA175A331411	SALLAAA135A332353	SALLAAA135A333714
SALLAAA135A327806	SALLAAA135A331416	SALLAAA135A332403	SALLAAA135A333747
SALLAAA135A327807	SALLAAA135A331417	SALLAAA135A332472	SALLAAA135A333766
SALLAAA135A327812	SALLAAA135A331418	SALLAAA135A332495	SALLAAA135A333803
SALLAAA135A327814	SALLAAA135A331420	SALLAAA135A332557	SALLAAA135A333837
SALLAAA135A327817	SALLAAA175A331422	SALLAAA135A332567	SALLAAA135A333866
SALLAAA135A327850	SALLAAA135A331425	SALLAAA175A332578	SALLAAA135A333874
SALLAAA135A327895	SALLAAA135A331426	SALLAAA135A332583	SALLAAA135A333876
SALLAAA135A327901	SALLAAA135A331442	SALLAAA135A332593	SALLAAA135A333879
SALLAAA135A327903	SALLAAA135A331445	SALLAAA135A332657	SALLAAA135A333881
SALLAAA135A327979	SALLAAA135A331483	SALLAAA135A332662	SALLAAA135A333914
SALLAAA135A328139	SALLAAA135A331515	SALLAAA135A332698	SALLAAA135A333915
SALLAAA135A328175	SALLAAA135A331521	SALLAAA135A332718	SALLAAA135A333947
SALLAAA135A328183	SALLAAA135A331523	SALLAAA175A332731	SALLAAA135A334032
SALLAAA135A328347	SALLAAA135A331524	SALLAAA135A332916	SALLAAA135A334038
SALLAAA135A328386	SALLAAA135A331529	SALLAAA135A332926	SALLAAA135A334047
SALLAAA135A328470	SALLAAA175A331533	SALLAAA135A332932	SALLAAA135A334098
SALLAAA135A328475	SALLAAA135A331549	SALLAAA135A332940	SALLAAA135A334134
SALLAAA135A328544	SALLAAA135A331584	SALLAAA135A332946	SALLAAA135A334147
SALLAAA135A328937	SALLAAA135A331591	SALLAAA135A332951	SALLAAA135A334185
SALLAAA135A328946	SALLAAA175A331600	SALLAAA175A332961	SALLAAA135A334189
SALLAAA135A328960	SALLAAA135A331621	SALLAAA135A332982	SALLAAA135A334209
SALLAAA135A328975	SALLAAA135A331683	SALLAAA135A333066	SALLAAA135A334239
SALLAAA135A328981	SALLAAA135A331703	SALLAAA135A333072	SALLAAA135A334305
SALLAAA135A328998	SALLAAA135A331758	SALLAAA135A333078	SALLAAA135A334347
SALLAAA135A329011	SALLAAA175A331759	SALLAAA135A333083	SALLAAA135A334493
SALLAAA135A329014	SALLAAA135A331760	SALLAAA175A333088	SALLAAA135A334517
SALLAAA135A329020	SALLAAA135A331763	SALLAAA135A333124	SALLAAA135A334548
SALLAAA135A329022	SALLAAA135A331800	SALLAAA135A333180	SALLAAA135A334633
SALLAAA135A329039	SALLAAA135A331823	SALLAAA175A333190	SALLAAA135A334765
SALLAAA135A329046	SALLAAA135A331824	SALLAAA135A333195	SALLAAA135A334813
SALLAAA135A329076	SALLAAA135A331835	SALLAAA135A333224	SALLAAA135A334969
SALLAAA135A329111	SALLAAA175A331846	SALLAAA135A333347	SALLAAA135A334993
SALLAAA135A329144	SALLAAA175A331887	SALLAAA135A333352	SALLAAA135A335013
SALLAAA135A329356	SALLAAA135A331903	SALLAAA135A333362	SALLAAA135A335020
SALLAAA175A329446	SALLAAA135A331915	SALLAAA175A333367	SALLAAA135A335122
SALLAAA175A329589	SALLAAA135A331917	SALLAAA135A333376	SALLAAA135A335155
SALLAAA175A330040	SALLAAA175A331919	SALLAAA135A333381	SALLAAA135A335206
SALLAAA175A330070	SALLAAA135A331921	SALLAAA135A333408	SALLAAA135A335238

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA135A335243	SALLAAA135A336449	SALLAAA135A338353	SALLAAA135A339745
SALLAAA135A335284	SALLAAA135A336460	SALLAAA135A338358	SALLAAA135A339765
SALLAAA135A335411	SALLAAA135A336469	SALLAAA135A338444	SALLAAA135A339774
SALLAAA135A335415	SALLAAA175A336470	SALLAAA135A338532	SALLAAA135A339790
SALLAAA135A335424	SALLAAA135A336471	SALLAAA135A338556	SALLAAA135A339791
SALLAAA135A335429	SALLAAA135A336489	SALLAAA135A338579	SALLAAA135A339821
SALLAAA135A335475	SALLAAA135A336497	SALLAAA135A338591	SALLAAA135A339845
SALLAAA135A335506	SALLAAA135A336607	SALLAAA135A338624	SALLAAA135A339851
SALLAAA135A335519	SALLAAA135A336625	SALLAAA135A338749	SALLAAA135A339861
SALLAAA175A335537	SALLAAA135A336646	SALLAAA135A338756	SALLAAA135A339866
SALLAAA135A335547	SALLAAA175A336682	SALLAAA135A338762	SALLAAA135A339890
SALLAAA135A335553	SALLAAA135A336772	SALLAAA135A338992	SALLAAA135A339892
SALLAAA135A335575	SALLAAA135A336789	SALLAAA135A338999	SALLAAA135A339902
SALLAAA135A335589	SALLAAA175A336820	SALLAAA135A339000	SALLAAA135A339917
SALLAAA135A335596	SALLAAA135A336826	SALLAAA135A339004	SALLAAA135A339967
SALLAAA135A335644	SALLAAA135A337036	SALLAAA135A339005	SALLAAA135A339971
SALLAAA135A335651	SALLAAA175A337039	SALLAAA175A339011	SALLAAA135A340094
SALLAAA175A335668	SALLAAA135A337056	SALLAAA135A339013	SALLAAA135A340120
SALLAAA135A335695	SALLAAA135A337207	SALLAAA135A339018	SALLAAA135A340122
SALLAAA135A335737	SALLAAA135A337225	SALLAAA135A339024	SALLAAA135A340198
SALLAAA135A335748	SALLAAA135A337228	SALLAAA135A339043	SALLAAA135A340199
SALLAAA135A335827	SALLAAA135A337378	SALLAAA135A339151	SALLAAA135A340201
SALLAAA135A335934	SALLAAA135A337383	SALLAAA135A339250	SALLAAA135A340202
SALLAAA135A335987	SALLAAA135A337386	SALLAAA135A339257	SALLAAA135A340203
SALLAAA135A335993	SALLAAA135A337388	SALLAAA135A339261	SALLAAA135A340224
SALLAAA135A336017	SALLAAA135A337393	SALLAAA135A339264	SALLAAA135A340244
SALLAAA135A336037	SALLAAA135A337399	SALLAAA135A339271	SALLAAA135A340386
SALLAAA135A336044	SALLAAA135A337404	SALLAAA135A339274	SALLAAA135A340420
SALLAAA135A336068	SALLAAA135A337409	SALLAAA135A339277	SALLAAA135A340423
SALLAAA135A336074	SALLAAA135A337417	SALLAAA135A339278	SALLAAA135A340515
SALLAAA135A336109	SALLAAA135A337451	SALLAAA135A339285	SALLAAA135A340534
SALLAAA135A336116	SALLAAA135A337461	SALLAAA135A339316	SALLAAA135A340606
SALLAAA135A336191	SALLAAA135A337463	SALLAAA135A339393	SALLAAA135A340614
SALLAAA135A336210	SALLAAA135A337481	SALLAAA135A339437	SALLAAA135A340622
SALLAAA135A336228	SALLAAA135A337497	SALLAAA135A339489	SALLAAA135A340640
SALLAAA135A336261	SALLAAA135A337548	SALLAAA135A339500	SALLAAA135A340674
SALLAAA135A336266	SALLAAA135A337589	SALLAAA135A339502	SALLAAA135A340704
SALLAAA135A336318	SALLAAA135A337606	SALLAAA135A339512	SALLAAA135A340710
SALLAAA135A336323	SALLAAA135A337621	SALLAAA135A339517	SALLAAA135A340770
SALLAAA135A336332	SALLAAA135A337927	SALLAAA135A339531	SALLAAA135A340844
SALLAAA135A336348	SALLAAA135A338014	SALLAAA135A339536	SALLAAA135A340849
SALLAAA135A336352	SALLAAA135A338031	SALLAAA135A339547	SALLAAA135A340878
SALLAAA135A336359	SALLAAA135A338085	SALLAAA135A339550	SALLAAA135A340887
SALLAAA135A336380	SALLAAA135A338101	SALLAAA135A339602	SALLAAA135A340889
SALLAAA135A336393	SALLAAA135A338197	SALLAAA135A339623	SALLAAA135A340902
SALLAAA175A336411	SALLAAA135A338239	SALLAAA135A339640	SALLAAA135A340917
SALLAAA135A336419	SALLAAA135A338275	SALLAAA135A339656	SALLAAA135A340930
SALLAAA135A336426	SALLAAA135A338300	SALLAAA135A339667	SALLAAA135A340940
SALLAAA135A336433	SALLAAA135A338315	SALLAAA135A339717	SALLAAA135A340950
SALLAAA175A336435	SALLAAA135A338333	SALLAAA135A339729	SALLAAA135A340958

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA135A341040	SALLAAA135A343711	SALLAAA135A344888	SALLAAA135A347640
SALLAAA135A341051	SALLAAA135A343739	SALLAAA135A344941	SALLAAA135A347732
SALLAAA135A341054	SALLAAA135A343744	SALLAAA135A344945	SALLAAA135A347735
SALLAAA135A341058	SALLAAA135A343825	SALLAAA135A344965	SALLAAA135A347746
SALLAAA135A341065	SALLAAA135A343840	SALLAAA135A344982	SALLAAA135A347749
SALLAAA135A341066	SALLAAA135A343848	SALLAAA135A345120	SALLAAA135A347767
SALLAAA135A341071	SALLAAA135A343871	SALLAAA135A345121	SALLAAA135A347784
SALLAAA135A341075	SALLAAA135A343894	SALLAAA135A345123	SALLAAA135A347871
SALLAAA135A341083	SALLAAA135A343899	SALLAAA135A345126	SALLAAA135A347893
SALLAAA135A341086	SALLAAA135A343917	SALLAAA135A345127	SALLAAA135A347907
SALLAAA135A341088	SALLAAA135A343931	SALLAAA135A345129	SALLAAA135A347910
SALLAAA135A341103	SALLAAA135A343955	SALLAAA135A345130	SALLAAA135A347913
SALLAAA135A341114	SALLAAA135A343958	SALLAAA135A345230	SALLAAA135A347953
SALLAAA135A341116	SALLAAA135A343964	SALLAAA135A345295	SALLAAA135A347956
SALLAAA135A341145	SALLAAA135A343969	SALLAAA135A345360	SALLAAA135A347962
SALLAAA135A341147	SALLAAA135A343982	SALLAAA135A345371	SALLAAA135A347973
SALLAAA135A341156	SALLAAA135A343992	SALLAAA135A345430	SALLAAA135A348003
SALLAAA135A341158	SALLAAA135A344010	SALLAAA135A345434	SALLAAA135A348006
SALLAAA135A341199	SALLAAA135A344067	SALLAAA135A345464	SALLAAA135A348009
SALLAAA135A341202	SALLAAA135A344075	SALLAAA135A345498	SALLAAA135A348024
SALLAAA135A341206	SALLAAA135A344080	SALLAAA135A345588	SALLAAA135A348027
SALLAAA135A341214	SALLAAA135A344087	SALLAAA135A345731	SALLAAA135A348033
SALLAAA135A341218	SALLAAA135A344108	SALLAAA135A345745	SALLAAA135A348035
SALLAAA135A341220	SALLAAA135A344188	SALLAAA135A345801	SALLAAA135A348038
SALLAAA135A341221	SALLAAA135A344241	SALLAAA135A345846	SALLAAA135A348044
SALLAAA135A341228	SALLAAA135A344246	SALLAAA135A345847	SALLAAA135A348050
SALLAAA135A341237	SALLAAA135A344251	SALLAAA135A345884	SALLAAA135A348053
SALLAAA135A341818	SALLAAA135A344253	SALLAAA135A346035	SALLAAA135A348056
SALLAAA135A341823	SALLAAA135A344258	SALLAAA135A346872	SALLAAA135A348085
SALLAAA135A341867	SALLAAA135A344277	SALLAAA135A347016	SALLAAA135A348091
SALLAAA135A342918	SALLAAA135A344317	SALLAAA135A347019	SALLAAA135A348103
SALLAAA135A342924	SALLAAA135A344323	SALLAAA135A347022	SALLAAA135A348110
SALLAAA135A342934	SALLAAA135A344355	SALLAAA135A347031	SALLAAA135A348114
SALLAAA135A343117	SALLAAA135A344386	SALLAAA135A347065	SALLAAA135A348117
SALLAAA135A343151	SALLAAA135A344388	SALLAAA135A347079	SALLAAA135A348118
SALLAAA135A343176	SALLAAA135A344400	SALLAAA135A347088	SALLAAA135A348120
SALLAAA135A343266	SALLAAA135A344413	SALLAAA135A347090	SALLAAA135A348123
SALLAAA135A343390	SALLAAA135A344422	SALLAAA135A347094	SALLAAA135A348133
SALLAAA135A343393	SALLAAA135A344555	SALLAAA135A347100	SALLAAA135A348134
SALLAAA135A343424	SALLAAA135A344568	SALLAAA135A347111	SALLAAA135A348135
SALLAAA135A343458	SALLAAA135A344571	SALLAAA135A347129	SALLAAA135A348137
SALLAAA135A343551	SALLAAA135A344574	SALLAAA135A347141	SALLAAA135A348143
SALLAAA135A343558	SALLAAA135A344580	SALLAAA135A347144	SALLAAA135A348146
SALLAAA135A343590	SALLAAA135A344586	SALLAAA135A347176	SALLAAA135A348155
SALLAAA135A343606	SALLAAA135A344633	SALLAAA135A347469	SALLAAA135A348161
SALLAAA135A343640	SALLAAA135A344763	SALLAAA135A347470	SALLAAA135A348167
SALLAAA135A343653	SALLAAA135A344818	SALLAAA135A347493	SALLAAA135A348170
SALLAAA135A343657	SALLAAA135A344844	SALLAAA135A347569	SALLAAA135A348179
SALLAAA135A343675	SALLAAA135A344865	SALLAAA135A347573	SALLAAA135A348196
SALLAAA135A343710	SALLAAA135A344880	SALLAAA135A347623	SALLAAA135A348202

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA135A348211	SALLAAA135A348897	SALLAAA135A349616	SALLAAA136A350207
SALLAAA135A348223	SALLAAA135A348913	SALLAAA135A349631	SALLAAA136A350215
SALLAAA135A348225	SALLAAA135A348939	SALLAAA135A349653	SALLAAA136A350220
SALLAAA135A348227	SALLAAA135A348977	SALLAAA135A349658	SALLAAA136A350222
SALLAAA135A348229	SALLAAA135A348983	SALLAAA135A349676	SALLAAA136A350225
SALLAAA135A348235	SALLAAA135A348995	SALLAAA135A349688	SALLAAA136A350250
SALLAAA135A348238	SALLAAA135A348998	SALLAAA135A349723	SALLAAA136A350256
SALLAAA135A348241	SALLAAA135A349004	SALLAAA135A349746	SALLAAA136A350258
SALLAAA135A348243	SALLAAA135A349007	SALLAAA135A349780	SALLAAA136A350272
SALLAAA135A348246	SALLAAA135A349033	SALLAAA135A349795	SALLAAA136A350276
SALLAAA135A348249	SALLAAA135A349036	SALLAAA135A349829	SALLAAA136A350284
SALLAAA135A348264	SALLAAA135A349044	SALLAAA135A349845	SALLAAA136A350288
SALLAAA135A348275	SALLAAA135A349049	SALLAAA135A349882	SALLAAA136A350429
SALLAAA135A348276	SALLAAA135A349061	SALLAAA135A349893	SALLAAA136A350433
SALLAAA135A348284	SALLAAA135A349067	SALLAAA135A349908	SALLAAA136A350435
SALLAAA135A348293	SALLAAA135A349071	SALLAAA135A349932	SALLAAA136A350498
SALLAAA135A348304	SALLAAA135A349077	SALLAAA136A349963	SALLAAA136A350521
SALLAAA135A348306	SALLAAA135A349080	SALLAAA136A349965	SALLAAA136A350861
SALLAAA135A348309	SALLAAA135A349088	SALLAAA136A349969	SALLAAA136A350865
SALLAAA135A348311	SALLAAA135A349090	SALLAAA136A350006	SALLAAA136A350866
SALLAAA135A348314	SALLAAA135A349098	SALLAAA136A350009	SALLAAA136A350868
SALLAAA135A348325	SALLAAA135A349103	SALLAAA136A350013	SALLAAA136A350871
SALLAAA135A348330	SALLAAA135A349109	SALLAAA136A350015	SALLAAA136A350873
SALLAAA135A348337	SALLAAA135A349123	SALLAAA136A350019	SALLAAA136A350874
SALLAAA135A348342	SALLAAA135A349136	SALLAAA136A350023	SALLAAA136A350876
SALLAAA135A348344	SALLAAA135A349164	SALLAAA136A350025	SALLAAA136A350877
SALLAAA135A348352	SALLAAA135A349166	SALLAAA136A350027	SALLAAA136A350881
SALLAAA135A348359	SALLAAA135A349170	SALLAAA136A350029	SALLAAA136A350882
SALLAAA135A348362	SALLAAA135A349174	SALLAAA136A350031	SALLAAA136A350888
SALLAAA135A348372	SALLAAA135A349175	SALLAAA136A350045	SALLAAA136A350890
SALLAAA135A348404	SALLAAA135A349177	SALLAAA136A350079	SALLAAA136A350893
SALLAAA135A348471	SALLAAA135A349179	SALLAAA136A350089	SALLAAA136A350895
SALLAAA135A348544	SALLAAA135A349188	SALLAAA136A350099	SALLAAA136A350922
SALLAAA135A348559	SALLAAA135A349194	SALLAAA136A350103	SALLAAA136A350939
SALLAAA135A348563	SALLAAA135A349200	SALLAAA136A350107	SALLAAA136A350993
SALLAAA135A348568	SALLAAA135A349403	SALLAAA136A350111	SALLAAA136A351012
SALLAAA135A348593	SALLAAA135A349408	SALLAAA136A350113	SALLAAA136A351148
SALLAAA135A348595	SALLAAA135A349409	SALLAAA136A350117	SALLAAA136A351285
SALLAAA135A348613	SALLAAA135A349428	SALLAAA136A350123	SALLAAA136A351315
SALLAAA135A348625	SALLAAA135A349430	SALLAAA136A350127	SALLAAA136A351318
SALLAAA135A348629	SALLAAA135A349432	SALLAAA136A350137	SALLAAA136A351339
SALLAAA135A348632	SALLAAA135A349434	SALLAAA136A350139	SALLAAA136A351342
SALLAAA135A348634	SALLAAA135A349436	SALLAAA136A350153	SALLAAA136A351384
SALLAAA135A348638	SALLAAA175A349438	SALLAAA136A350154	SALLAAA136A351425
SALLAAA135A348742	SALLAAA135A349450	SALLAAA136A350163	SALLAAA136A352146
SALLAAA135A348757	SALLAAA135A349502	SALLAAA136A350183	SALLAAA136A352259
SALLAAA135A348788	SALLAAA135A349504	SALLAAA136A350185	SALLAAA136A352260
SALLAAA135A348855	SALLAAA135A349518	SALLAAA136A350193	SALLAAA136A352291
SALLAAA135A348859	SALLAAA135A349601	SALLAAA136A350197	SALLAAA136A352295
SALLAAA135A348861	SALLAAA135A349615	SALLAAA136A350205	SALLAAA136A352302



VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA136A352365	SALLAAA136A352940	SALLAAA136A356270	SALLAAA136A357255
SALLAAA136A352389	SALLAAA136A352949	SALLAAA136A356285	SALLAAA136A357274
SALLAAA136A352407	SALLAAA136A352952	SALLAAA136A356298	SALLAAA136A357281
SALLAAA136A352440	SALLAAA136A352954	SALLAAA136A356307	SALLAAA136A357295
SALLAAA136A352461	SALLAAA136A352966	SALLAAA136A356320	SALLAAA136A357327
SALLAAA136A352485	SALLAAA136A352974	SALLAAA136A356327	SALLAAA136A357329
SALLAAA136A352498	SALLAAA136A352978	SALLAAA136A356363	SALLAAA136A357351
SALLAAA136A352561	SALLAAA136A352979	SALLAAA136A356479	SALLAAA136A357353
SALLAAA136A352566	SALLAAA136A353047	SALLAAA136A356491	SALLAAA136A357355
SALLAAA136A352568	SALLAAA136A353089	SALLAAA136A356499	SALLAAA136A357358
SALLAAA136A352787	SALLAAA136A353112	SALLAAA136A356525	SALLAAA136A357377
SALLAAA136A352791	SALLAAA136A353127	SALLAAA136A356547	SALLAAA136A357379
SALLAAA136A352793	SALLAAA136A353132	SALLAAA136A356559	SALLAAA136A357381
SALLAAA136A352794	SALLAAA136A353175	SALLAAA136A356565	SALLAAA136A357389
SALLAAA136A352795	SALLAAA136A353223	SALLAAA136A356579	SALLAAA136A357391
SALLAAA136A352797	SALLAAA136A353273	SALLAAA136A356585	SALLAAA136A357393
SALLAAA136A352798	SALLAAA136A353434	SALLAAA136A356623	SALLAAA136A357424
SALLAAA136A352800	SALLAAA136A354034	SALLAAA136A356663	SALLAAA136A357433
SALLAAA136A352801	SALLAAA136A354035	SALLAAA136A356669	SALLAAA136A357449
SALLAAA136A352802	SALLAAA136A354037	SALLAAA136A356715	SALLAAA136A357451
SALLAAA136A352803	SALLAAA136A355034	SALLAAA136A356751	SALLAAA136A357500
SALLAAA136A352804	SALLAAA136A355046	SALLAAA136A356761	SALLAAA136A357517
SALLAAA136A352805	SALLAAA136A355072	SALLAAA136A356763	SALLAAA136A357527
SALLAAA136A352807	SALLAAA136A355074	SALLAAA136A356765	SALLAAA136A357538
SALLAAA136A352813	SALLAAA136A355080	SALLAAA136A356777	SALLAAA136A357554
SALLAAA136A352816	SALLAAA136A355090	SALLAAA136A356779	SALLAAA136A357555
SALLAAA136A352823	SALLAAA136A355325	SALLAAA136A356799	SALLAAA136A357568
SALLAAA136A352837	SALLAAA136A355327	SALLAAA136A356801	SALLAAA136A357657
SALLAAA136A352843	SALLAAA136A355329	SALLAAA136A356817	SALLAAA136A357754
SALLAAA136A352845	SALLAAA136A355708	SALLAAA136A356847	SALLAAA136A357949
SALLAAA136A352847	SALLAAA136A355753	SALLAAA136A356864	SALLAAA136A357954
SALLAAA136A352848	SALLAAA136A355765	SALLAAA136A356874	SALLAAA136A358026
SALLAAA136A352849	SALLAAA136A355847	SALLAAA136A356880	SALLAAA136A358059
SALLAAA136A352855	SALLAAA136A355932	SALLAAA136A356982	SALLAAA136A358072
SALLAAA136A352866	SALLAAA136A355956	SALLAAA136A357016	SALLAAA136A358073
SALLAAA136A352873	SALLAAA136A356016	SALLAAA136A357119	SALLAAA136A358088
SALLAAA136A352874	SALLAAA136A356022	SALLAAA136A357123	SALLAAA136A358096
SALLAAA136A352878	SALLAAA136A356048	SALLAAA136A357128	SALLAAA136A358113
SALLAAA136A352885	SALLAAA136A356055	SALLAAA136A357129	SALLAAA136A358141
SALLAAA136A352894	SALLAAA136A356077	SALLAAA136A357133	SALLAAA136A358148
SALLAAA136A352898	SALLAAA136A356084	SALLAAA136A357135	SALLAAA136A358187
SALLAAA136A352899	SALLAAA136A356089	SALLAAA136A357137	SALLAAA136A358195
SALLAAA136A352902	SALLAAA136A356095	SALLAAA136A357151	SALLAAA136A358215
SALLAAA136A352905	SALLAAA136A356137	SALLAAA136A357155	SALLAAA136A358216
SALLAAA136A352909	SALLAAA136A356144	SALLAAA136A357173	SALLAAA136A358217
SALLAAA136A352921	SALLAAA136A356159	SALLAAA136A357175	SALLAAA136A358247
SALLAAA136A352923	SALLAAA136A356167	SALLAAA136A357241	SALLAAA136A358265
SALLAAA136A352933	SALLAAA136A356198	SALLAAA136A357250	SALLAAA136A358279
SALLAAA136A352935	SALLAAA136A356246	SALLAAA136A357251	SALLAAA136A358283
SALLAAA136A352937	SALLAAA136A356268	SALLAAA136A357253	SALLAAA136A358311

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA136A358319	SALLAAA136A359304	SALLAAA136A360516	SALLAAA136A361717
SALLAAA136A358343	SALLAAA136A359382	SALLAAA136A360559	SALLAAA136A361760
SALLAAA136A358349	SALLAAA136A359412	SALLAAA136A360566	SALLAAA136A361848
SALLAAA136A358366	SALLAAA136A359414	SALLAAA136A360619	SALLAAA136A361914
SALLAAA136A358377	SALLAAA136A359426	SALLAAA136A360621	SALLAAA136A361929
SALLAAA136A358381	SALLAAA136A359432	SALLAAA136A360637	SALLAAA136A361960
SALLAAA136A358391	SALLAAA136A359466	SALLAAA136A360778	SALLAAA136A361975
SALLAAA136A358407	SALLAAA136A359488	SALLAAA136A360785	SALLAAA136A361994
SALLAAA136A358409	SALLAAA136A359497	SALLAAA136A360812	SALLAAA136A362047
SALLAAA136A358410	SALLAAA136A359513	SALLAAA136A360826	SALLAAA136A362049
SALLAAA136A358413	SALLAAA136A359518	SALLAAA136A360841	SALLAAA136A362052
SALLAAA136A358428	SALLAAA136A359523	SALLAAA136A360869	SALLAAA136A362080
SALLAAA136A358439	SALLAAA136A359537	SALLAAA136A360877	SALLAAA136A362086
SALLAAA136A358444	SALLAAA136A359541	SALLAAA136A360890	SALLAAA136A362107
SALLAAA136A358465	SALLAAA136A359556	SALLAAA136A360893	SALLAAA136A362112
SALLAAA136A358481	SALLAAA136A359567	SALLAAA136A360899	SALLAAA136A362114
SALLAAA136A358487	SALLAAA136A359573	SALLAAA136A360911	SALLAAA136A362166
SALLAAA136A358497	SALLAAA136A359575	SALLAAA136A360937	SALLAAA136A362174
SALLAAA136A358507	SALLAAA136A359579	SALLAAA136A360965	SALLAAA136A362179
SALLAAA136A358533	SALLAAA136A359595	SALLAAA136A360975	SALLAAA136A362193
SALLAAA136A358535	SALLAAA136A359601	SALLAAA136A360980	SALLAAA136A362196
SALLAAA136A358541	SALLAAA136A359612	SALLAAA136A360986	SALLAAA136A362199
SALLAAA136A358546	SALLAAA136A359619	SALLAAA136A360989	SALLAAA136A362205
SALLAAA136A358563	SALLAAA136A359621	SALLAAA136A360994	SALLAAA136A362210
SALLAAA136A358577	SALLAAA136A359622	SALLAAA136A360999	SALLAAA136A362237
SALLAAA136A358593	SALLAAA136A359631	SALLAAA136A361025	SALLAAA136A362242
SALLAAA136A358595	SALLAAA136A359641	SALLAAA136A361031	SALLAAA136A362249
SALLAAA136A358604	SALLAAA136A359657	SALLAAA136A361037	SALLAAA136A362258
SALLAAA136A358644	SALLAAA136A359673	SALLAAA136A361068	SALLAAA136A362270
SALLAAA136A358692	SALLAAA136A359717	SALLAAA136A361070	SALLAAA136A362274
SALLAAA136A358720	SALLAAA136A359731	SALLAAA136A361102	SALLAAA136A362286
SALLAAA136A358724	SALLAAA136A359732	SALLAAA136A361128	SALLAAA136A362291
SALLAAA136A358758	SALLAAA136A359736	SALLAAA136A361177	SALLAAA136A362303
SALLAAA136A358760	SALLAAA136A359742	SALLAAA136A361194	SALLAAA136A362312
SALLAAA136A358806	SALLAAA136A359745	SALLAAA136A361198	SALLAAA136A362332
SALLAAA136A358814	SALLAAA136A359751	SALLAAA136A361211	SALLAAA136A362334
SALLAAA136A358850	SALLAAA136A359753	SALLAAA136A361224	SALLAAA136A362346
SALLAAA136A358860	SALLAAA136A359763	SALLAAA136A361228	SALLAAA136A362349
SALLAAA136A358902	SALLAAA136A359773	SALLAAA136A361248	SALLAAA136A362356
SALLAAA136A358908	SALLAAA136A359783	SALLAAA136A361252	SALLAAA136A362358
SALLAAA136A358992	SALLAAA136A359795	SALLAAA136A361318	SALLAAA136A362379
SALLAAA136A359084	SALLAAA136A359824	SALLAAA136A361326	SALLAAA136A362389
SALLAAA136A359090	SALLAAA136A359849	SALLAAA136A361332	SALLAAA136A362391
SALLAAA136A359092	SALLAAA136A360057	SALLAAA136A361344	SALLAAA136A362401
SALLAAA136A359140	SALLAAA136A360062	SALLAAA136A361358	SALLAAA136A362405
SALLAAA136A359156	SALLAAA136A360214	SALLAAA136A361446	SALLAAA136A362412
SALLAAA136A359164	SALLAAA136A360227	SALLAAA136A361475	SALLAAA136A362427
SALLAAA176A359174	SALLAAA136A360282	SALLAAA136A361481	SALLAAA136A362442
SALLAAA136A359192	SALLAAA136A360298	SALLAAA136A361515	SALLAAA136A362444
SALLAAA136A359245	SALLAAA136A360464	SALLAAA136A361634	SALLAAA136A362446

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLAAA136A362473	SALLAAA136A363520	SALLAAA136A364089	SALLAAA136A365401
SALLAAA136A362482	SALLAAA136A363528	SALLAAA136A364094	SALLAAA136A365406
SALLAAA136A362489	SALLAAA136A363539	SALLAAA136A364134	SALLAAA136A365411
SALLAAA136A362497	SALLAAA136A363542	SALLAAA136A364187	SALLAAA136A365414
SALLAAA136A362509	SALLAAA136A363549	SALLAAA136A364198	SALLAAA136A365421
SALLAAA136A362515	SALLAAA136A363551	SALLAAA136A364207	SALLAAA136A365428
SALLAAA136A362516	SALLAAA136A363560	SALLAAA136A364213	SALLAAA136A365434
SALLAAA136A362518	SALLAAA136A363569	SALLAAA136A364216	SALLAAA136A365439
SALLAAA136A362519	SALLAAA136A363585	SALLAAA136A364224	SALLAAA136A365446
SALLAAA136A362521	SALLAAA136A363592	SALLAAA136A364230	SALLAAA136A365448
SALLAAA136A362529	SALLAAA136A363595	SALLAAA136A364234	SALLAAA136A365453
SALLAAA136A362658	SALLAAA136A363602	SALLAAA136A364247	SALLAAA136A365459
SALLAAA136A362686	SALLAAA136A363603	SALLAAA136A364251	SALLAAA136A365477
SALLAAA136A362688	SALLAAA136A363615	SALLAAA136A364252	SALLAAA136A365527
SALLAAA136A362832	SALLAAA136A363647	SALLAAA136A364341	SALLAAA136A365540
SALLAAA136A362833	SALLAAA136A363652	SALLAAA136A364371	SALLAAA136A365637
SALLAAA136A362835	SALLAAA136A363665	SALLAAA136A364373	SALLAAA136A365664
SALLAAA136A362909	SALLAAA136A363669	SALLAAA136A364377	SALLAAA136A365747
SALLAAA136A362913	SALLAAA136A363671	SALLAAA136A364384	SALLAAA136A365796
SALLAAA136A362954	SALLAAA136A363681	SALLAAA136A364395	SALLAAA136A365881
SALLAAA136A362959	SALLAAA136A363684	SALLAAA136A364404	SALLAAA136A366147
SALLAAA136A362982	SALLAAA136A363696	SALLAAA136A364434	SALLAAA136A366196
SALLAAA136A362991	SALLAAA136A363701	SALLAAA136A364532	SALLAAA136A366198
SALLAAA136A363083	SALLAAA136A363711	SALLAAA136A364617	SALLAAA136A366212
SALLAAA136A363086	SALLAAA136A363715	SALLAAA136A364674	SALLAAA136A366229
SALLAAA136A363092	SALLAAA136A363722	SALLAAA136A364679	SALLAAA136A366418
SALLAAA136A363097	SALLAAA136A363733	SALLAAA136A364695	SALLAAA136A366420
SALLAAA136A363117	SALLAAA136A363738	SALLAAA136A364704	SALLAAA136A366518
SALLAAA136A363135	SALLAAA136A363743	SALLAAA136A364721	SALLAAA136A366736
SALLAAA136A363188	SALLAAA136A363749	SALLAAA136A364764	SALLAAA136A366754
SALLAAA136A363220	SALLAAA136A363752	SALLAAA136A364766	SALLAAA136A366788
SALLAAA136A363230	SALLAAA136A363754	SALLAAA136A364796	SALLAAA136A366804
SALLAAA136A363270	SALLAAA136A363756	SALLAAA136A364844	SALLAAA136A367053
SALLAAA136A363274	SALLAAA136A363759	SALLAAA136A364894	SALLAAA136A367072
SALLAAA136A363301	SALLAAA136A363767	SALLAAA136A364901	SALLAAA136A367085
SALLAAA136A363314	SALLAAA136A363776	SALLAAA136A364920	SALLAAA135A331945
SALLAAA136A363328	SALLAAA136A363785	SALLAAA136A364921	
SALLAAA136A363330	SALLAAA136A363792	SALLAAA136A364947	
SALLAAA136A363361	SALLAAA136A363803	SALLAAA136A365034	
SALLAAA136A363366	SALLAAA136A363808	SALLAAA136A365037	
SALLAAA136A363380	SALLAAA136A363816	SALLAAA136A365038	
SALLAAA136A363382	SALLAAA136A363825	SALLAAA136A365074	
SALLAAA136A363391	SALLAAA136A363889	SALLAAA136A365093	
SALLAAA136A363409	SALLAAA136A363914	SALLAAA136A365205	
SALLAAA136A363411	SALLAAA136A363944	SALLAAA136A365219	
SALLAAA136A363421	SALLAAA136A364030	SALLAAA136A365279	
SALLAAA136A363437	SALLAAA136A364034	SALLAAA136A365285	
SALLAAA136A363445	SALLAAA136A364042	SALLAAA136A365371	
SALLAAA136A363470	SALLAAA136A364071	SALLAAA136A365372	
SALLAAA136A363499	SALLAAA136A364076	SALLAAA136A365398	

VIN - EU3	VIN - EU3	VIN - EU3	VIN - EU3
SALLSAA135A905387	SALLSAA135A906159	SALLSAA135A908077	SALLSAA136A913765
SALLSAA135A905402	SALLSAA135A906160	SALLSAA135A908081	SALLSAA136A913774
SALLSAA135A905404	SALLSAA135A906199	SALLSAA135A908102	SALLSAA136A913789
SALLSAA135A905410	SALLSAA135A906265	SALLSAA135A908261	SALLSAA136A913791
SALLSAA135A905413	SALLSAA135A906271	SALLSAA135A908338	SALLSAA136A913864
SALLSAA135A905416	SALLSAA135A906446	SALLSAA135A908339	SALLSAA136A913911
SALLSAA135A905451	SALLSAA135A906588	SALLSAA135A908340	SALLSAA136A913917
SALLSAA135A905488	SALLSAA135A906646	SALLSAA135A908419	SALLSAA136A913931
SALLSAA135A905489	SALLSAA135A906671	SALLSAA135A908535	SALLSAA136A913933
SALLSAA135A905501	SALLSAA135A906724	SALLSAA135A908573	SALLSAA136A913939
SALLSAA135A905503	SALLSAA135A906760	SALLSAA135A908598	SALLSAA136A913975
SALLSAA135A905508	SALLSAA135A906776	SALLSAA135A908601	SALLSAA136A913997
SALLSAA135A905549	SALLSAA135A906796	SALLSAA135A908622	SALLSAA136A914002
SALLSAA135A905551	SALLSAA135A906797	SALLSAA135A908656	SALLSAA136A914489
SALLSAA135A905572	SALLSAA135A906798	SALLSAA135A908741	SALLSAA136A914492
SALLSAA135A905574	SALLSAA135A906805	SALLSAA135A908757	SALLSAA136A914494
SALLSAA135A905575	SALLSAA135A906820	SALLSAA135A908779	SALLSAA136A914505
SALLSAA135A905577	SALLSAA135A906832	SALLSAA135A908798	SALLSAA136A914947
SALLSAA135A905578	SALLSAA135A906833	SALLSAA135A908832	SALLSAA136A914954
SALLSAA135A905589	SALLSAA135A906851	SALLSAA135A908847	SALLSAA136A914976
SALLSAA135A905590	SALLSAA135A906897	SALLSAA135A908934	SALLSAA136A915001
SALLSAA135A905591	SALLSAA135A906943	SALLSAA135A909082	SALLSAA136A915037
SALLSAA135A905602	SALLSAA135A906976	SALLSAA135A909254	SALLSAA136A915045
SALLSAA135A905679	SALLSAA135A906982	SALLSAA135A909443	SALLSAA136A915056
SALLSAA135A905740	SALLSAA135A906988	SALLSAA135A909466	SALLSAA136A915127
SALLSAA135A905753	SALLSAA135A907001	SALLSAA135A909479	SALLSAA136A915149
SALLSAA135A905755	SALLSAA135A907012	SALLSAA135A909514	SALLSAA136A915152
SALLSAA135A905791	SALLSAA135A907032	SALLSAA135A909519	SALLSAA136A915164
SALLSAA135A905808	SALLSAA135A907078	SALLSAA135A909562	SALLSAA136A915167
SALLSAA135A905820	SALLSAA135A907088	SALLSAA135A909852	SALLSAA136A915352
SALLSAA135A906003	SALLSAA135A907105	SALLSAA135A910060	SALLSAA136A915627
SALLSAA135A906006	SALLSAA135A907250	SALLSAA135A910538	SALLSAA136A915628
SALLSAA135A906021	SALLSAA135A907302	SALLSAA135A910577	SALLSAA136A915630
SALLSAA135A906115	SALLSAA135A907771	SALLSAA135A910584	SALLSAA136A915631
SALLSAA135A906119	SALLSAA135A907841	SALLSAA135A910591	SALLSAA136A915634
SALLSAA135A906122	SALLSAA135A907868	SALLSAA135A910616	SALLSAA136A915687
SALLSAA135A906123	SALLSAA135A907873	SALLSAA135A910714	SALLSAA136A915818
SALLSAA135A906124	SALLSAA135A907877	SALLSAA135A910823	SALLSAA136A916118
SALLSAA135A906125	SALLSAA135A907886	SALLSAA135A911458	SALLSAA136A916437
SALLSAA135A906126	SALLSAA135A907894	SALLSAA135A911659	SALLSAA136A916533
SALLSAA135A906127	SALLSAA135A907898	SALLSAA135A911714	SALLSAA136A916653
SALLSAA135A906130	SALLSAA135A907902	SALLSAA135A911827	SALLSAA136A916917
SALLSAA135A906133	SALLSAA135A907909	SALLSAA135A911837	SALLSAA136A916925
SALLSAA135A906136	SALLSAA135A907919	SALLSAA136A912715	SALLSAA136A917006
SALLSAA135A906140	SALLSAA135A907923	SALLSAA136A912717	SALLSAA136A917011
SALLSAA135A906141	SALLSAA135A908053	SALLSAA136A912788	SALLSAA136A917014
SALLSAA135A906146	SALLSAA135A908054	SALLSAA136A912910	SALLSAA136A917016
SALLSAA135A906154	SALLSAA135A908056	SALLSAA136A913055	SALLSAA136A917027
SALLSAA135A906155	SALLSAA135A908060	SALLSAA136A913231	SALLSAA136A917035
SALLSAA135A906156	SALLSAA135A908061	SALLSAA136A913745	SALLSAA136A917038



VIN - EU3	VIN - EU3	VIN - EU3	VIN EU3
SALLSAA136A917052	SALLSAA136A920133	SALLSAA136A924088	SALLSAA136A928929
SALLSAA136A917071	SALLSAA136A920209	SALLSAA136A924292	SALLSAA136A928950
SALLSAA136A917134	SALLSAA136A920315	SALLSAA136A924298	SALLSAA136A928954
SALLSAA136A917201	SALLSAA136A920349	SALLSAA136A924347	SALLSAA136A928980
SALLSAA136A918105	SALLSAA136A920361	SALLSAA136A924350	SALLSAA136A929048
SALLSAA136A918142	SALLSAA136A920459	SALLSAA136A925220	
SALLSAA136A918143	SALLSAA136A921028	SALLSAA136A925283	
SALLSAA136A918168	SALLSAA136A921177	SALLSAA136A925317	
SALLSAA136A918187	SALLSAA136A921193	SALLSAA136A925319	
SALLSAA136A918225	SALLSAA136A921369	SALLSAA136A925336	
SALLSAA136A918230	SALLSAA136A921417	SALLSAA136A925365	
SALLSAA136A918254	SALLSAA136A921429	SALLSAA136A925367	
SALLSAA136A918255	SALLSAA136A921545	SALLSAA136A925393	
SALLSAA136A918405	SALLSAA136A921556	SALLSAA136A925399	
SALLSAA136A918407	SALLSAA136A921649	SALLSAA136A925400	
SALLSAA136A918417	SALLSAA136A921677	SALLSAA136A925421	
SALLSAA136A918434	SALLSAA136A921704	SALLSAA136A926216	
SALLSAA136A918442	SALLSAA136A921742	SALLSAA136A926244	
SALLSAA136A918445	SALLSAA136A921746	SALLSAA136A926265	
SALLSAA136A918469	SALLSAA136A921758	SALLSAA136A926279	
SALLSAA136A918484	SALLSAA136A921768	SALLSAA136A926283	
SALLSAA136A918505	SALLSAA136A922569	SALLSAA136A926291	
SALLSAA136A918525	SALLSAA136A922579	SALLSAA136A926368	
SALLSAA136A918537	SALLSAA136A922581	SALLSAA136A926377	
SALLSAA136A918560	SALLSAA136A922594	SALLSAA136A926404	
SALLSAA136A918621	SALLSAA136A922600	SALLSAA136A926413	
SALLSAA136A918752	SALLSAA136A922614	SALLSAA136A926418	
SALLSAA136A918783	SALLSAA136A922659	SALLSAA136A926421	
SALLSAA136A918801	SALLSAA136A922661	SALLSAA136A926470	
SALLSAA136A918833	SALLSAA136A922679	SALLSAA136A926478	
SALLSAA136A918845	SALLSAA136A922820	SALLSAA136A926505	
SALLSAA136A918915	SALLSAA136A922829	SALLSAA136A926511	
SALLSAA136A919083	SALLSAA136A922837	SALLSAA136A926524	
SALLSAA136A919134	SALLSAA136A922865	SALLSAA136A926525	
SALLSAA136A919207	SALLSAA136A922882	SALLSAA136A926532	
SALLSAA136A919262	SALLSAA136A922989	SALLSAA136A926544	
SALLSAA136A919313	SALLSAA136A922998	SALLSAA136A926554	
SALLSAA136A919319	SALLSAA136A922999	SALLSAA136A926564	
SALLSAA136A919466	SALLSAA136A923111	SALLSAA136A926570	
SALLSAA136A919642	SALLSAA136A923115	SALLSAA136A926602	
SALLSAA136A919758	SALLSAA136A923282	SALLSAA136A926658	
SALLSAA136A919759	SALLSAA136A923838	SALLSAA136A926680	
SALLSAA136A919760	SALLSAA136A923842	SALLSAA136A926684	
SALLSAA136A919762	SALLSAA136A923857	SALLSAA136A926705	
SALLSAA136A919766	SALLSAA136A923860	SALLSAA136A926711	
SALLSAA136A919767	SALLSAA136A923947	SALLSAA136A926739	
SALLSAA136A919828	SALLSAA136A923948	SALLSAA136A926787	
SALLSAA136A920008	SALLSAA136A923965	SALLSAA136A926822	
SALLSAA136A920059	SALLSAA136A924053	SALLSAA136A926860	
SALLSAA136A920127	SALLSAA136A924074	SALLSAA136A927081	