
Removal of three heat shields necessary in front N/S wheel well. Take care noting exactly how they are removed to ensure they can be replaced easily



View of turbo area before being cleaned up and hose replaced



View of turbo clean up and hose replaced



Old hose removed and section of new hose before trimming

